

PASSTCERT

QUESTION & ANSWER

Higher Quality
Better Service!

We offer free update service for one year
[HTTP://WWW.PASSTCERT.COM](http://www.passtcert.com)

Exam : **API-571**

Title : Corrosion and Materials
Professional

Version : DEMO

1. _____ is the main concern during start-up, shutdown and/or hydro testing for equipment/piping operating at elevated temperatures. This event can also occur in an auto refrigeration event in units processing light hydrocarbons.

- A. Stress fracture
- B. Carburization
- C. Spheroidization
- D. Brittle fracture

Answer: D

2. Fatigue will not occur in carbon steel if stresses are below the:

- A. Transition limit.
- B. Endurance limit.
- C. Hardening limit.
- D. Speed limit.

Answer: B

3. _____ has been a major problem on coke drum shells.

- A. Thermal fatigue
- B. Stress cracking
- C. Erosion
- D. Temper embrittlement

Answer: A

4. The "L" grade of stainless steels will sensitize if exposed more than several hours above _____ or long term above _____.

- A. 1200° F, 800° F
- B. 1000°, 600° F
- C. 1000° F, 750° F
- D. 1100° F, 800° F

Answer: C

5. Once cracking from LME has occurred, grinding out the affected area _____ an acceptable fix.

- A. Is
- B. Is not
- C. Can be
- D. Can not be

Answer: B