PASSTCERT QUESTION & ANSWER

Higher Quality
Better Service!

We offer free update service for one year HTTP://WWW.PASSTCERT.COM

Exam : HP0-429

Title : Installing&Supporting

Standerd HP SAN

Environments

Version: DEMO

1. Which security mechanism describes hard zoning?

A.login authentication

B.access authorization

C.network authentication

D.discovery authorization

Correct:B

2. What can cause a changed hardware path to a connected disk after a switch replacement in an HP-UX environment with multiple B-Series switches? (Select two.)

A.Zoning on the new switch is not configured correctly.

B.Simple Name Service is not copied to the new switch.

C.Core switch PID format parameter differs from the old one.

D.New switch has a domain ID which differs from the old one.

E.Disk (storage controller port) is connected to a different switch port.

Correct:D E

3.An HAFM (High Availability Fabric Manager) appliance must be shut down for maintenance reasons. Which operations are not interrupted?

A.logging events

B.switch monitoring

C.Fibre Channel traffic

D.configuration changes

Correct:C

4. You are replacing the active control processor card, CTP2, of an M-series Director switch. Which action is required before removing the CTP?

A.Shut down CTP2.

B.Make CTP2 passive.

C.Power off the switch.

D.Shut down the switch.

Correct:B

5. You are adding a new switch to an existing environment. How can you avoid fabric segmentation?

A.Assign unique domain IDs to the switches.

B.Register all domain IDs in the fabric name service.

C.Set up trusts between switches with different domain IDs.

D.Assign the same domain IDs to all switches connected by ISLs.

Correct:A

6. What is the maximum number of addressable ports per B-series switch running in Native Address mode?

8.A

B.16

C.32

D.64

Correct:B

7. What is the best method to consolidate C-Series SAN islands into a common infrastructure without compromising availability, manageability and network security?

A.Zone the SAN.

B.Configure LSANs.

C.Implement VSANs.

D.Link islands with multi-protocol router.

Correct:C

8. Which M-series feature key is required to implement fabric binding and switch binding?

A.SANtegrity

B.Open Trunking

C.FICON management server

D.open systems management server

Correct:A

9. You add a switch to a B-series fabric. Its IP address is unknown, so you must use the serial port. Which port attributes must be configured in the terminal emulation in addition to 8 bit, no parity,1 stop bit?

A.9600baud, no flow control

B.19200baud, no flow control

C.9600baud, hardware flow control

D.19200baud, hardware flow control

Correct:A

10.To solve a customer problem, a remote login to a recently installed High Availability Fabric Manager appliance is required. The customer does not know the username and password. Which factory default login should be used?

A.admin / password

B.Administrator / password

C.administrator / Password

D.Administrator / Administrator

Correct:B