PASSTCERT QUESTION & ANSWER

Higher Quality
Better Service!

We offer free update service for one year HTTP://WWW.PASSTCERT.COM

Exam : HP0-513

Title : AlphaServer System

Maintenance (formerIt

#330-610)

Version: DEMO

1. Where can you check an AlphaServer's serial number for warranty status?
A. SRL
B. CSN
C. QRL
D. OMNI
Answer: B
2. Which type of PCI bus slot is available on an AlphaServer DS10L?
A. 16-bit
B. 32-bit
C. 64-bit
D. 128-bit
Answer: C
3. Which AlphaServer does NOT have an interlock switch?
A. DS10
B. DS20
C. DS20E
D. ES40
Answer: A
4. When installing a new Alpha system, which command would you use with the Loadable Firmware Utility
(LFU) to verify option firmware revision level?
A. check
B. update
C. show revision
D. list
Answer: D

5. On an AlphaServer ES40, what information is obtained from the "show fru -e" command?

A. FRU firmware version
B. extended fru status
C. FRU environmental variables
D. FRU with errors
Answer: D
6. Alpha console firmware updates can be performed using all of the following, EXCEPT
A. CD-ROM
B. floppy disk
C. the network
D. replacing the chip
Answer: D
7. Which FRUs are defined as hot-pluggable on the AlphaServer DS20?
A. individual fans
B. hard drives
C. PCI options
D. power supplies
Answer: B
8. What is ONE of the configuration rules when installing DIMMs on an AlphaServer ES40?
A. One DIMM in each memory motherboard.
B. Fill odd memory sets first.
C. Fill even memory sets first.
D. Fill sets in numerical order.
Answer: D
9. When an AlphaServer DS20 has correctable memory errors, what action does the system take?
A. crashes and re-boots
B. halts to console

C. resets
D. continues running
Answer: D
10. Which file contains the Tru64 UNIX startup and error information?
A. event.log
B. messages
C. sysfile
D. errorlog.sys
Answer: B
11. Which component is hot-swappable on the ES40?
A. fan
B. CPU
C. memory
D. PCI option
Answer: A
12. What must be considered when installing an AlphaServer DS20?
A. Do not install the system under a desk.
B. Do not install the rear of the system against a wall.
C. Install the system only in a computer room.
D. The system must be installed in a rack.
Answer: B
13. AlphaServer firmware upgrades are performed for what purpose? Select TWO.
A. Add new hardware support.
B. Recognize new memory.
C. Remove old options.
D. Perform firmware bug fixes.

E. Rebuild kernel.
Answer: AD
14. Which command option overrides any setting of the boot_osflags environment variable?
A flags
B osflags
C boot
D vars
Answer: A
15. Which background process must be running for Compaq Analyze to function?
A. desta_exec
B. analyze_exec
C. webes_exec
D. ca_exec
Answer: A
16. If you remove a PCI option card and do not replace it, what is the necessary action you must take?
16. If you remove a PCI option card and do not replace it, what is the necessary action you must take?A. Replace the PCI option cover.
A. Replace the PCI option cover.
A. Replace the PCI option cover. B. No action necessary.
A. Replace the PCI option cover. B. No action necessary. C. Install a filler PCI airflow card.
A. Replace the PCI option cover.B. No action necessary.C. Install a filler PCI airflow card.D. Terminate the PCI slot.
A. Replace the PCI option cover.B. No action necessary.C. Install a filler PCI airflow card.D. Terminate the PCI slot.
 A. Replace the PCI option cover. B. No action necessary. C. Install a filler PCI airflow card. D. Terminate the PCI slot. Answer: A
 A. Replace the PCI option cover. B. No action necessary. C. Install a filler PCI airflow card. D. Terminate the PCI slot. Answer: A 17. Which SRM console environment variable identifies the SCSI controller ID?
A. Replace the PCI option cover. B. No action necessary. C. Install a filler PCI airflow card. D. Terminate the PCI slot. Answer: A 17. Which SRM console environment variable identifies the SCSI controller ID? A. pk*_host_id
A. Replace the PCI option cover. B. No action necessary. C. Install a filler PCI airflow card. D. Terminate the PCI slot. Answer: A 17. Which SRM console environment variable identifies the SCSI controller ID? A. pk*_host_id B. SCSI_ID

18. Which URL invokes Compaq Analyze on the local node?
A. http://localhost :7902
B. http://localhost :80
C. http://localhost :1705
D. http://localhost :2981
Answer: A
19. Two additional CPUs have been added to ES40. After the addition of these CPUs, the system does
not initialize properly. What could resolve this problem?
A. More cache needs to be added.
B. A second power supply is needed.
C. A second cabinet fan needs to be added.
D. Add a voltage regulator for each CPU.
Answer: B
20. Which SRM command is used to verify the proper functioning of the system components during
system installation?
A. test
B. diag
C. boot
D. sysex
Answer: A