

PASSTCERT

QUESTION & ANSWER

Higher Quality
Better Service!

We offer free update service for one year
[HTTP://WWW.PASSTCERT.COM](http://www.passtcert.com)

Exam : **640-792**

Title : Supporting Cisco
TelePresence System
Devices v1.0 (TPTECH)

Version : Demo

1.Which port is indicated on the right Secondary Codec for the CTS-3210?

- A. Right Display
- B. Right Camera
- C. Center Display
- D. Left Display

Answer: B

2.Which port do you conned to on the Primary Codec in order to establish an Ethernet connection between your laptop and the Cisco TelePresence 3000 equipment.?

- A. Video port
- B. Network port
- C. IP Phone port
- D. Secondary Camera port

Answer: B

3.Which size and type of tool is required to loosen the screws that allow rotational adjustment of the CTS-3010 cameras?

- A. #1 Phillips screwdriver
- B. 5.0 mm Allen wrench
- C. #3 Phillips screwdriver
- D. 3.0 mm Allen wrench

Answer: D

4.Which four functions does Cisco TelePresence rely on Cisco Unified Communications Manager for? (Choose four)

- A. Configurations
- B. Software upgrades
- C. Management
- D. Call processing
- E. Scheduling meetings
- F. Microphone calibration


Answer: A,C,D,E

5.Which three of the following components are included on the Cisco TelePresence 3210? (Choose three.)


- A. One boardroom-style table with a second row
- B. One boardroom-style table
- C. One 40" external display
- D. Nine table microphones
- E. Four LED light fixtures

Answer: A,C,D

6.DRAG DROP



Answer:



7. Which three of the following are benefits of Cisco TelePresence Manager? (Choose three)

- A. Bulk software upgrades of endpoints
- B. Calendaring integration and management
- C. One-Button-to-Push meeting access
- D. Allow for content sharing
- E. Concierge services

Answer: B,C,D

8. Which two hardware components are optional for the Cisco TelePresence 1000? (Choose two)

- A. One Cisco Unified IP Phone 7975G
- B. One external display
- C. One high-definition camera
- D. One Auxiliary Control Unit

Answer: A,D

9. Which port is indicated on the Auxiliary Control Unit for the CTS-1100 and 1300?



- A. Auxiliary Collaboration Display
- B. Serial Control for Projector
- C. Lights
- D. Serial Control for Dimmer Box

Answer: B

10.DRAG DROP

Click and drag the Cisco TelePresence model on the left to the number of participants the unit is designed for on the right:

CTS-500	2 participants in a multipurpose room
CTS-1100	Up to 18 participants in dedicated TelePresence room
CTS-1300	1-2 participants in a home/executive Office
CTS-3010	6 participants in a multipurpose room
CTS-3210	6 participants in a dedicated TelePresence room

Answer:

Click and drag the Cisco TelePresence model on the left to the number of participants the unit is designed for on the right.

CTS-500	CTS-1100
CTS-1100	CTS-3210
CTS-1300	CTS-500
CTS-3010	CTS-1300
CTS-3210	CTS-3010